C.T.L 9

Notice to Mariners No. 23 of 1929.

Marine Department, Wellington, N.Z., 11th May, 1929.

NEW ZEALAND.—NORTH ISLAND.—WEST COAST.—WANGANUI HARBOUR.

Changes in River Lights and Leading-beacons.

1. Position of Mole-end Lights to be altered.

2. River Rear Lighted Leading-beacon to be installed.
3. Putiki Lighted Leading-beacon to be discontinued. 4. Landguard Bluff Lighted Leading-beacon to be discontinued.

Position: Lat. 39° 57½' S., long. 175° 03' E. (approx.). Date of Change: 29th May, 1929.

1. Alteration: The two fixed red lights, situated one each at the seaward ends of North and South Moles, are to be moved to a position 40 ft. (approx.) shoreward from the extremity of each mole.

2. Details: A white rear lighted leading-beacon exhibiting a flashing white light is to be installed southward of the South Half-tide Training Wall at the point where the upper and lower sailing courses intersect. This beacon will be situated 228½° 750 ft. from the upper red beacon, and 106° 440 ft. from the present position of the middle red beacon.

Remarks: This beacon is to be used as a rear leadingbeacon for both the upper and lower sailing courses, and it will take the place of the rear lighted leading-beacons at Putiki and at the east end of Landguard Bluff, both of which latter are to be discontinued.

3. Details: The white rear lighted leading-beacon exhibit-

ing a flashing white light, situated at Putiki, is to be

Remarks: This beacon is used as a rear beacon in conjunction with the middle red beacon for the purpose of marking the lower sailing course.

4. Details: The white rear lighted leading-beacon exhibiting a fixed white light, situated at the east end of Landguard Bluff, is to be discontinued.

Remarks: This beacon is used as a rear beacon in con-

junction with the upper red beacon for the purpose of marking the upper sailing course.

Chart affected: 2588.

Publications: New Zealand Pilot, 1919, page 101; New Zealand Nautical Almanac and Tide-tables, 1929, page 227.

Authority: Wanganui Harbour Board, 8/5/29.

G. C. GODFREY, Secretary.

(M. 3/13/307.)

Notice to Mariners No. 24 of 1929.

Marine Department, Wellington, N.Z., 14th May, 1929.

NEW ZEALAND.—SOUTH ISLAND.—EAST COAST.—TIMARU HARBOUR.

1. Eastern Extension Mole Lights discontinued.

2. Temporary Leading Lights installed.

Position: Lat. 44° 24′ S., long. 171° 19′ E. (approx.).
1. Details: The two green lights situated at the outer end of the Eastern Extension Mole have been discontinued owing to damage resulting from heavy weather.

Remarks: It is intended to replace the two green lights by one flashing white light.

 Details: Two fixed red lights, 1,032 ft. apart, in transit 267½°, visible four miles, the front light 57 ft. and the rear light 80 ft. in height, have been installed on Benvenue Cliff northward of the town. The front light is situated 3291° 3,730 ft. from Timaru Harbour Lighthouse; and the arc of visibility of each light

emarks: These lights in transit lead 700 ft. (approx.) northward of the outer end of the Eastern Extension Remarks: Mole; and they have been erected on poles which are not useable as day marks.

Chart affected: 2532.

Publications: List of Lights, 1927, Part VI, No. 3604;

New Zealand Pilot, 1919, page 351; New Zealand Nautical

Almanac and Tide-tables, 1929, page 163, No. 125, page 267, and plan facing page 268.

Authority: Timaru Harbour Board, 9/5/29.

(M. 4/49.)

G. C. GODFREY, Secretary.

CROWN LANDS NOTICES.

Lands in the Auckland Land District forfeited.

Department of Lands and Survey, Wellington, 13th May, 1929.

NOTICE is hereby given that the leases and licenses of the undermentioned lands having been declared forfeited by resolution of the Auckland Land Board, the said lands have thereby reverted to the Crown under the provisions of the Land Act, 1924, and the Discharged Soldiers Settlement Act, 1915, and amendments.

AUCKLAND LAND DISTRICT.

	Tenu	e.	Lease or License No.	Section.	Block.	Survey District.	Lessee or Licensee.	Reason for Forfeiture.
	D.S.	299		5 .	xvi	Moketu	A. F. Amadio	Non - compliance with conditions of lease.
*	D.S. O.R.P.	••	641 1469	2 9	V VI	Hurakia Awaroa	W. M. Peterson S. J. Miller	Ditto. Non - compliance with conditions of license.
	D.P.	••	1010	6 and 7	V	Moturiki Township	W. Greening	Ditto.

JAS. B. DONALD, for Minister of Lands.

Land in Taranaki Land District forfeited.

Department of Lands and Survey, Wellington, 8th May, 1929. OTICE is hereby given that the leases and licenses of the undermentioned lands having been declared forfeited by resolution of the Taranaki Land Roard the residual to the Undermentioned lands having been declared forfeited by resolution of the Taranaki Land Board, the said lands have thereby reverted to the Crown under the provisions of the Land Act, 1924.

SCHEDULE.

TARANAKI LAND DISTRICT.

Tenure.	Lease No.	Section.	Block.	Survey District.	Lessee.	Reason for Forfeiture.
0.R.P 0.R.P 0.R.P I.F.O.R.P. R.L	978 824 856 20 8	12 7 1 10 7	I X I XI XVI	Pouatu Mapara Omara Mapara Ohura	C. W. H. Frank M. Le Long A. Hamilton W. J. J. Wainwright F. Bloomfield	Non-compliance with conditions of license. At request. Non-compliance with conditions of license. At request.